



[1.4567]

M	$\frac{SW}{2}$	l			
M4	0,5 - 2,5	11,0			500
	2,0 - 4,0	12,5			500
SW 6,0	SW² 6,8	k 0,5	l₁ max. 8,5	\curvearrowright 5 Nm	\updownarrow 6000 N
M5	0,5 - 3,0	12,0			500
	3,0 - 4,5	13,5			500
SW 7,0	SW² 8,0	k 0,5	l₁ max. 9,0	\curvearrowright 7 Nm	\updownarrow 9500 N
M6	0,5 - 3,0	14,0			500
	3,0 - 5,0	16,0			500
SW 9,0	SW² 10,0	k 0,5	l₁ max. 10,0	\curvearrowright 13 Nm	\updownarrow 16000 N

M	$\frac{SW}{2}$	l			
M8	0,5 - 3,0	16,0			250
	3,0 - 5,5	18,5			250
SW 11,0	SW² 12,0	k 0,5	l₁ max. 11,5	\curvearrowright 25 Nm	\updownarrow 26000 N
M10	1,0 - 3,5	19,0			250
SW 13,0	SW² 14,4	k 0,7	l₁ max. 14,0	\curvearrowright 55 Nm	\updownarrow 39000 N
M12	1,0 - 4,0	24,0			100
SW 16,0	SW² 17,3	k 0,7	l₁ max. 19,0	\curvearrowright 85 Nm	\updownarrow 55000 N